

TECH TIP

Ford Radiator Fan Motor

There may be several reasons for Radiator Fan Motors not to fit the applications other than a catalog errors.

The first possibility as to why the Radiator fan motor will not fit the application, is if the entire fan assembly has been replaced instead of just the radiator motor. Some of the Fan assemblies that have been installed use a different motor than original equipment. If this is the case, our OE replacement fan will not always fit the application. Sometimes a part number off the radiator fan motor may be helpful. If no match is found you may have to replace the entire assembly instead of just the motor.

Another situation to be aware of is that we are replacing many two speed Ford radiator fan motors with a one speed motor. When we cut out the low fan speed and go directly to a high speed, the vehicle will get back to operating temperatures faster. This will prolong vehicle life and discourage engine temps from creeping to unwanted temperatures. NOTE: There may be a wiring harness difference that will require hard-wiring.

