

# TECH TIP

## Chrysler Mini-Van Belt Squeal 1996 - 2000

In Tech Tip #4S 415, we discussed this problem as it pertained to the air conditioning system and gave ideas of different causes for this problem.

In addition to the squeal, there is a problem with the belt coming off. This tip discusses a belt and pulley replacement kit.

This kit eliminates the smooth back idler pulley. The replacement pulleys are all grooved. The belt is grooved on both sides making a positive gripping contact on all surfaces.

Kit number 4S 45780 fits 1996 – 2000 Chrysler mini-vans with 3.3 and 3.8 engines.

Kit number 4S 45781 fits 1996 – 2000 Chrysler mini-vans with 3.0 engine.

